

# SAFETY RECALL

April 2014

## Important Safety Notice

### White-Rodgers Announces Voluntary Corrective Action on Model 1F80-04xx, 1F83-04xx, 1F85-04xx, 1F86-04xx Thermostats



1F80-04xx



1F83-04xx





1F85-04xx




1F86-04xx

**Hazard:** Leakage from the “AA” alkaline batteries used in the thermostat can result in a shorting of portions of the printed circuit board which may present a potential fire hazard.


**Affected Models:** The potentially affected thermostats have a battery door on top and either 3 or 4 buttons to the right of the screen. Only thermostats which do not show a battery icon  on the thermostat screen are affected. All thermostats with date codes after the 1<sup>st</sup> week of 2014 (also marked with a green dot ●) are not affected.



Only thermostats **without** a battery icon require action.



No Action Required



Action Required

**Remedy:** Consumers should contact White-Rodgers for assistance with product identification and corrective action or visit the White-Rodgers website. For affected thermostats, a packet will be sent which includes instructions on the corrective action.

For more information, contact **1-888-624-1901**.

Or visit the White-Rodgers' recall website at **[www.regcen.com/1f8recall](http://www.regcen.com/1f8recall)**