

IMPORTANT SAFETY INFORMATION

White-Rodgers, in cooperation with the U.S. Consumer Product Safety Commission and Health Canada, is implementing a corrective action plan that affects some installations of the Model 1F8x-04xx Thermostats. **Leakage from the “AA” alkaline batteries used in the thermostat can result in a shorting of portions of the printed circuit board which may present a potential fire hazard.**

The potentially affected thermostats include all Model 1F80-04xx, 1F83-04xx, 1F85-04xx and 1F86-04xx thermostats manufactured before the 50th week of 2013. The thermostats can be identified by the battery door on the top of the thermostat and 3 or 4 buttons to the right of the blue thermostat screen. Only thermostats which do not show a battery icon  on the thermostat screen are affected. All thermostats with date codes after the 1st week of 2014 (also marked with a green dot ●) are not affected.

Consumers - If you have a Model 1F8x-04xx thermostat without a battery icon , contact White-Rodgers toll-free at **1-888-624-1901** or on line at **www.regcen.com/1f8recall**. A corrective action packet will be sent to your home.

IMPORTANT SAFETY NOTICE

REGARDING WHITE-RODGERS MODEL 1F8x-04xx THERMOSTATS

Distributors / Installers - Please check all thermostats in your inventory. If you have any Model 1F8x-04xx Thermostats, please call **1-888-624-1901** for assistance and so that White-Rodgers can arrange to refund the purchase price upon return of the thermostats.



1F80-04xx



1F83-04xx




1F85-04xx





1F86-04xx

Hazard: Leakage from the “AA” alkaline batteries used in the thermostat can result in a shorting of portions of the printed circuit board which may present a potential fire hazard.

Affected Models: The potentially affected thermostats have a battery door on top and either 3 or 4 buttons to the right of the screen.



Only thermostats **without** a battery icon require action.



Remedy: Customers with a 1F8X-04XX thermostat that **does not** show a battery icon  on the thermostat screen should contact White-Rodgers for assistance with the corrective action or visit the White-Rodgers website.